Operator: WHITE COUNTY HOUSING AUTHORITY	Operator ID#: 39072
Inspection Date(s): 1/31/2014 (Half)	Man Days: 0.5
Inspection Unit: WHITE COUNTY HOUSING AUTHORITY	
Location of Audit: Olney	
Exit Meeting Contact: Mike Wendling, USDI	
Inspection Type: Standard Inspection - Record Audit	
Pipeline Safety Representative(s): Jim Watts	
Company Representative to Receive Report: Brad Raley	
Company Representative's Email Address: bradr@ilgas.com	

Headquarters Address Information:	1927 Miller Drive	
	Olney, IL 62450	
	Emergency Phone#:	
	Fax#:	
Official or Mayor's Name:	Darin Houchin	
	Phone#: (618) 392-5502	
	Email:	
Inspection Contact(s)	Title	Phone No.
Mike Wendling	1927 Miller Drive	
Mike Wendling	Gas Engineer - USDI	

Status
Crossville, Grayville and Norris City Municipals
Not Applicable
•
Not Applicable

No calculated due to the Master Meter not being required	if to file an annual report.	
Number of Services		Not Checked
General Comment:		
USDI does not maintain a service count as they do not file	e an annual report.	
Miles of Main		1.1
Is the operator maintaining documentation ver	rifying their Maximum Allowable Operating Pressure(s)? (MAOP)	Satisfactory
General Comment:		
The operator has no test records from the installation so tw.c.").	they are using the prior operating history and have established the MAOP at 7 inc.	hes water column ("in
Operating Pressure (Feeder)		Not Applicable
General Comment:		-
White County has no feeder systems.		
Operating Pressure (Town)		7 inches water column
Operating Pressure (Other)		Not Applicable
General Comment:		•
There are no other pressure systems.		
MAOP (Feeder)		Not Applicable
General Comment:		•
No feeder piping.		
MAOP (Town)		7 inches water column
MAOP (Other)		Not Applicable
General Comment:		
No Other MAOP's		
Does the operator have any transmission pipe	elines?	No
Regulatory Reporting Records		Status
[191.5]	Were Telephonic Notices of Incidents reported to the NRC (800-424-8802)?	Not Applicable
General Comment:	·	
N/A No reportable incidents occurred in 2011-2013.		
[191.9(a)]	Was a DOT Incident Report Form F7100.1 submitted within 30 days after detection of an incident?	Not Applicable

General Comment:		
Master Meter operators are not required to f	ile written incident reports and there were no reportable incidents in 2011-2013.	
[191.9(b)]	Were any supplemental incident reports submitted when deemed necessary?	Not Applicable
General Comment:	•	
Not required to submit written incident repor	ts because they are a Master Meter Operator.	
Did the operator have any plastic pi	pe failures in the past calendar year?	No
General Comment:		
There were no plastic pipe failures in 2011-2	2013.	
Did the operator take action to mitig components?	pate safety concerns relating to the failure of the PE or pipeline	No
General Comment:		
There were no failures on plastic piping in 20	011-2013.	
[191.23(a)]	Did the operator report Safety Related Conditions?	Not Applicable
General Comment:		
There were no Safety Related conditions to	report in 2011-2013.	
[191.25]	Did the Operator file a Safety Related Condition Report within 5 working days of determination, but not later than 10 working days after discovery?	Not Applicable
General Comment:		
There were no Safety Related Conditions to	report in 2011-2013.	
[192.16(c)]	Customer Notification: Has the operator notified each new customer within 90 days about the customer's responsibility regarding buried piping, however, operators of a master meter may continuously post a general notice in a permanent location?	Satisfactory
General Comment:	•	
USDI provided a copy of the letter that is set tenants that the Housing Authority is not res	nt out annually in 2011-2013 and the posting that is placed at each of the White County Housin ponsible for any gas utilization equipment or piping installed by the tenant.	g Offices that warns
	DRUG TESTING	Status
Refer to Drug and Alcohol Inspection Forms and Protocols		Not Applicable
General Comment: Master Meter Operators are not required to	have a drug testing program. The USDI personnel who under contract perform operation, mair	ntenance and
emergency response activities for White Col	unty Housing are currently in a qualified Drug and Alconol testind brodram.	

[192.517(a)][192.505,192.507,192.511(c)]	Are pressure test records being maintained for piping operating above 100 psig?	Not Applicable
General Comment:		
N/A No piping operating at or above 100 psig in the White	County systems.	
[192.517(b)][192.511,192.509,192.513]	Are pressure test records being maintained for at least 5 years on piping operating below 100 psig?	Satisfactory
General Comment:		
	m. A 12 inch segment of the outlet riser on a master meter was replaced at the Mae leak was initially repaired with a bolt on leak clamp and was then permanently and recorded and retained the test records for this work.	
[192.603(b)][192.725]	Were service lines temporarily disconnected from the main properly tested prior to reconnection?	Satisfactory
General Comment:		
The system at Martin and 3rd in Grayville, was tested prior	r to reinstating to system pressure.	
	UPRATING	Status
Category Comment:		
No uprating was performed in 2011-2013 on the White Co	unty systems.	
[192.555][192.555]	Has the operator maintained documentation of uprating activities when uprating a pipe to a pressure that will produce a hoop stress of 30% or more SMYS?	Not Applicable
[192.557][192.557]	Has the operator maintained documentation of uprating activities when uprating a pipe to a pressure that will produce a hoop stress of less than 30% SMYS?	Not Applicable
	OPERATIONS	Status
[192.603(b)][192.605(a)]	Has the operator conducted a review of the Operations and Maintenance Manual once per yr/15 months?	Satisfactory
General Comment:	·	
The OM&E manual was reviewed as required in 2011-201	3.	
Has the operator conducted a review of the Op	perator Qualification Plan once per yr/15 months?	Yes
General Comment:		
The USDI/Illinois Gas OQ plan was reviewed as required in	in 2011-2013 and is conducted with the O&M review.	
[192.603(b)][192.605(b)(3)]	Are construction records, maps, and operating history available to operating personnel?	Satisfactory
General Comment:		
USDI is maintaining current maps and the associated reco	ords for White County Housing. Field personnel have access to these records or	maps at the Illinois
[192.603(b)][192.605(b)(8)]	Has the operator periodically reviewed personnel's work to	Not Applicable

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

	determine the effectiveness of normal O&M procedures when deficiencies are found?	
General Comment:	•	
USDI/Illinois Gas is performing field evaluations procedures during the inspections performed in	s of their personnel to determine if they are following current procedures and identified no is n 2012-2013.	sues with their
CONTI	NUING SURVEILLANCE RECORDS	Status
[192.603(b)][192.613(a)]	Has the operator reviewed continuing surveillance records for class location changes, failures, leak history, corrosion, changes in cathodic protection, and other unusual operating and maintenance conditions?	Satisfactory
General Comment:		
Continuing surveillance was conducted as requ	uired in 2011-2013.	
[192.491][192.489]	Does the operator have records verifying if exposed cast iron was examined for evidence of graphitization and if necessary what appropriate action was taken concerning graphitization?	Not Applicable
General Comment:	·	
N/A No cast iron in the White County systems.		
[192.603(b)][192.755]	Does the operator have surveillance records of cast iron pipelines, including appropriate action resulting from tracking circumferential cracking failures, study of leak history, or any other unusual operating and maintenance conditions?	Not Applicable
General Comment:	•	
N/A No cast iron in the White County systems.		
[192.603(b)][192.753(a)]	Is each cast iron caulked bell and spigot joint that is subject to a pressure of more than 25 (psig.) sealed as required?	Not Applicable
General Comment:	<u> </u>	
N/A No cast iron in the White County systems.		
[192.603(b)][192.753(b)]	Is each cast iron caulked bell and spigot joint that is subject to a pressure of 25 (psig.) or less and is exposed for any reason sealed as required?	Not Applicable
General Comment:	<u> </u>	
N/A No cast iron in the White County systems.		
QUALIFI	CATION OF PIPELINE PERSONNEL	Status
Refer to operator Qualification Inspec	tion Forms and Protocols	Yes
General Comment:		<u>I</u>
MALLITE COLINITY LIQUEING AUTHORITY/4 24		

WHITE COUNTY HOUSING AUTHORITY/1-31-2014

Page 5 of 16

Unless otherwise noted, all code references are to 49CFR Part 192.

If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Due to USDI being a contractor for White County Housing and the Housing having no qualified personnel, Staff reviewed the Illinois Gas/USDI OQ plan during a separate audit conducted in January 2014.

DAI	MAGE PREVENTION RECORDS	Status
[192.603(b)][191.11(a)]	Did the operator track the number of damages per 1000 locate requests for the previous years?	Satisfactory
General Comment:		
USDI performs all locates and retains the recollocates. In 2011-2013 there were no damages	rds for locate requests received for White County Housing. Due to this they can calculate th to report due to third party excavation.	e damages per 1000
Has the number of damages increase	d or decreased from prior year?	Same in 2011- 2013 No Damages
[192.603(b)][192.617]	Does the operator track records of accidents due to excavation damage to ensure causes of failures are addressed to minimize the recurrence?	Satisfactory
General Comment:	<u> </u>	•
There were no damages in 2011-2013.		
[192.603(b)][192.614(c)(3)]	Does the operator provide documentation pertaining to notification of excavation, marking, positive response, and the availability and use of the one call system?	Satisfactory
General Comment:	<u> </u>	•
Locate tickets were reviewed and found they warea was clear.	rere responded to and completed within the required intervals. Contact was made with the e	excavator when the
Does the operator have a Quality Ass facilities?	urance Program in place for monitoring the locating and marking of	Yes
General Comment:		
Supervisors are performing random job site eva completed evaluations and observed no issues	aluations to ensure their employees are completing the tasks as required by their procedures.	s. Staff reviewed the
Do pipeline operators include perform	ance measures in facility locating contracts?	No
General Comment:		•
Performance measures are not utilized or requ	ired.	
[IL ADM. CO.265.100(b)(1)]	Was third party damage to mains involving a release of gas reported to ICC JULIE Enforcement? http://www.icc.illinois.gov/julie/	Not Applicable
General Comment:	·	
N/A No damages or violations to report in 2011	-2013.	
Has the Operator adopted applicable	section of the Common Ground Alliance Best Practices?	Yes
General Comment:		
	able CGA best practices.	

If no, were Common Ground Alliance Best Practices discussed with Operator?		Not Applicable
General Comment:		
They have adopted the applicable best practices.		
	EMERGENCY PLANS	Status
[192.603(b)][192.615(b)(1)]	Are supervisors, responsible for emergency action, furnished copies of the latest edition of the Emergency Plan?	Satisfactory
General Comment:		•
Yes, emergency plans are provided to the supervis	sors.	
[192.603(b)][192.615(b)(2)]	Has the operator maintained documentation that the appropriate operating personnel have received training to assure they are knowledgeable of emergency procedures and that the training was effective?	Satisfactory
General Comment:		
Training was performed annually with all USDI/Illin	nois Gas personnel as required in 2011-2013.	
[192.603(b)][192.615(b)(3)]	Has the operator maintained documentation of employee activity reviews to determine whether the procedures were effectively followed in each emergency?	Not Applicable
General Comment:		
N/A No emergencies occurred that required review	vs to be conducted.	
[192.603(b)][192.615(c)]	Has the operator maintained documentation that the operator established and maintained liaison with appropriate fire, police and other public officials?	Satisfactory
General Comment:		
Liaison was performed as required with the local e	emergency agencies.	
[192.603(b)][192.615(a)(3)]	Did the review of emergency response time intervals regarding odor/leak complaint documentation indicate adequate emergency response intervals were achieved?	Satisfactory
General Comment:		
Review of the 2011-2013 leak reports indicate the identified.	y were responded to in a timely manner and corrective actions were taken when leaks or	safety hazards were
PUBLIC AW	VARENESS PROGRAM - RECORDS	Status
Refer to Public Awareness Program Insp	pection Forms and Protocols	Not Checked
General Comment:		1
The Public Awareness protocols were not reviewe gas safety awareness flyer in their offices at White	ed as part of this audit. Staff did review documentation indicating the housing authority has County Housing.	as posted the natural

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

00	OORIZATION OF GAS	Status
[192.603(b)][192.625(f)]	Has the operator maintained documentation of odorant concentration level testing using an instrument?	Satisfactory
General Comment:		
	owns where White County has systems as required. These were performed by the matter tecord as required in 2011-2013. USDI also performs an odorometer test when continuous	
[192.603(b)][192.625(e)]	Has the operator maintained documentation of odorizer tank levels?	Not Applicable
General Comment:		
N/A White County purchases odorized gas from the M	unicipal systems that serve their systems. White County has no odorizers in their sys	stems.
[192.603(b)][192.625(f)(1)]	Are master meter operators receiving written verification of odorant concentration levels from their gas supplier?	Satisfactory
General Comment:		
	owns where White County has systems as required. These were performed by the matter tecord as required in 2011-2013. USDI also performs an odorometer test when continuous	
[192.603(b)][192.625(f)(2)]	Has the master meter operator maintained documentation of sniff tests performed as required by this section?	Satisfactory
General Comment:		
USDI does perform annual odorometer tests during the	e leak survey to confirm the results they are receiving from the municipals.	
PATROL	LING & LEAKAGE SURVEY	Status
[192.603(b)][192.721(b)(1)]	Is the operator patrolling business districts at a minimum of 4 per year/4 1/2 months?	Not Applicable
General Comment:		
N/A No Business Districts in the White County System	s.	
[192.603(b)][192.721(b)(2)]	Is the operator patrolling outside business districts at a minimum of 2 per year/7 1/2 months?	Satisfactory
General Comment:		
Biannual patrols were conducted in the White County	systems in 2011-2013.	
[192.603(b)][192.723(b)(1)]	Is the operator performing leakage surveys in business districts at a minimum of 1 per year/ 15 months? If the operator has inside meter sets that meet this criterion then were those surveyed?	Not Applicable
General Comment:		
N/A No Business Districts in the White County System	s.	
[192.603(b)][192.723(b)(2)]	Is the operator performing leakage surveys outside a business district at a minimum of every 5 years/63	Satisfactory

WHITE COUNTY HOUSING AUTHORITY/1-31-2014

Page 8 of 16

PRESSURE LIM	TING AND REGULATION	Status
	abandoned onshore pipeline facility that crosses over, under or through a commercially navigable waterway?	Not Applicable
[192.603(b)][192.727(e)] [192.727(g)][192.727(g)]	Did the operator maintain documentation when air was used for purging that a combustible mixture was not present after purging? Did the operator maintain documentation for each	Not Applicable
[192.603(b)][192.727(d)]	Did the operator maintain documentation demonstrating that whenever service to a customer was discontinued access to gas was either; locked, prevented by a mechanical fitting, or disconnected from the gas supply and open pipe ends sealed?	Not Applicable
[192.603(b)][192.727(c)]	Did the operator maintain documentation demonstrating that each inactive pipeline that is not being maintained under this part was disconnected from all sources and supplies of gas; purged of gas?	Not Applicable
[192.603(b)][192.727(b)]	Did the operator maintain documentation demonstrating that each pipeline abandoned in place was disconnected from all sources and supplies of gas, and purged of gas?	Not Applicable
Category Comment: N/A No abandonments or deactivations were performed in 20	11-2013. White County has no piping that crosses a navigable waterway.	
ABANDONMENT or DEACTIVE	ATION of FACILITIES PROCEDURES	Status
[192.723(b)(1),192.723(b)(2)][220 ILCS 2.2.03]	After the determination of the cathodic protection requirements, has the operator surveyed each line within the required leakage survey intervals?	Not Applicable
[192.463,220 ILCS 2.2.03][220 ILCS 2.2.03]	Has the operator determined if cathodic protection is required on these services?	Not Applicable
[220 ILCS 2.2.03]	Has the operator designated and documented the location of all services where the meter is located more than 3 feet away from the wall of a residence?	Not Applicable
White County has no yard lines in their systems.		
Category Comment:		
	ES - RESIDENTIAL	Status
General Comment: Leak surveys were performed by USDI personnel annually in a	all of the White County systems in 2011-2013	
	operator has yard lines then are those being surveyed?	
	cathodically unprotected pipelines at a minimum of every 3 years/39 months? If the operator has inside meter sets that meet this criterion then were those surveyed? If the	
	months? Is the operator performing leakage surveys on	

Seneral Comment:	[192.603(b)][192.739(a)]	Is the operator inspecting and testing the pressure limiting and regulating stations at a minimum of 1 per year/15 months?	Not Applicable
Is the operator inspecting pressure limiting and regulating stations for adequate capacity at a minimum of 1 per year/15 months? Semeral Comment:	General Comment:	·	
stations for adequate capacity at a minimum of 1 per year/15 months? General Comment: There is no pressure regulation/overpressure protection owned or operated by White County Housing. The Municipals own and operate the Pressure regulation provide overpressure protection [192.603(b)][192.743(b)] If the operator used calculations to determine sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15 months? General Comment: USDI has evaluated the pressure regulation and overpressure protection present to ensure they have sufficient capacity. [192.603(b)][192.741(a),192.741(b)] Is each distribution system supplied by more than one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to indicate the gas pressure in the district? General Comment: NA All of the White County systems each have one source of supply. They are not currently monitored using pressure recording devices. [192.603(b)][192.741(c)] If there were indications of abnormally high- or low-pressure, were actions taken to correct any unsatisfactory operating conditions? General Comment: No reports of unusually high pressures were reported in 2011-2013. [192.603(b)][192.743(a),192.743(b),192.195(b)(2)] If Yes, does the operator have documentation to verify that these devices have adequate capacity? General Comment: USDI is to conduct a review the master meter installations and determine if they have adequate capacity provide overpressure protection and determine separate relief devices are present. If inadequate capacities are present. at these devices have adequate capacity to provide overpressure protection and determine separate relief devices are present. If inadequate capacities are present. at the provide overpressure protection and determine is they have adequate capacity to provide overpressure protection and determine separate relief devices are present. If inadequate		owned or operated by White County Housing. The Municipals own and operate th	e pressure regulators
There is no pressure regulation/overpressure protection owned or operated by White County Housing. The Municipals own and operate the Pressure regulation provide overpressure protection [192.603(b)][192.743(b)] [If the operator used calculations to determine sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15 months? [If the operator used calculations to determine sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15 months? [If the operator used calculations to determine sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15 months? [If the operator or used calculations to determine sufficient capacity. [If year, 15] [If year, 16] [If year, 16] [If year, 16] [If year, 16] [If year or or a system supplied by more than one district pressure regulating station, or where requirated by the operator or a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to indicate the gas pressure in the district? [If year, 16] [If there were indications of abnormally high- or low-pressure, were actions taken to correct any unsatisfactory operating conditions? [If year, 16] [If there were indications of abnormally high- or low-pressure, were actions taken to correct any unsatisfactory operating conditions? [If year, 16]	[192.603(b)][192.743(a)]	stations for adequate capacity at a minimum of 1 per	Not Applicable
[192.603(b)][192.743(b)] [If the operator used calculations to determine sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15 months? Satisfactor	General Comment:	•	
capacity, were the calculation reviews documented at a minimum of 1 per year/15 months? General Comment: USDI has evaluated the pressure regulation and overpressure protection present to ensure they have sufficient capacity. [192.603(b)][192.741(a),192.741(b)] Is each distribution system supplied by more than one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to indicate the gas pressure in the district? General Comment: N/A All of the White County systems each have one source of supply. They are not currently monitored using pressure recording devices. [192.603(b)][192.741(c)] If there were indications of abnormally high- or low-pressure, were actions taken to correct any unsatisfactory operating conditions? General Comment: No reports of unusually high pressures were reported in 2011-2013. [192.603(b)][192.743(a), 192.743(b), 192.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [192.603(b)][192.743(a)] If Yes, does the operator have documentation to verify that these devices have adequate capacity? General Comment: USDI is to conduct a review the master meter installations and determine if they have adequate capacity to provide overpressure protection and determine separate relief devices are present. If inadequate capacities are present, addition protection shall be installed. VALVE MAINTENANCE Status		owned or operated by White County Housing. The Municipals own and operate th	e Pressure regulators
USDI has evaluated the pressure regulation and overpressure protection present to ensure they have sufficient capacity. Is each distribution system supplied by more than one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to indicate the gas pressure in the district? Seeral Comment:	[192.603(b)][192.743(b)]	capacity, were the calculation reviews documented at a	Satisfactory
[192.603(b)][192.741(a),192.741(b)] Is each distribution system supplied by more than one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to indicate the gas pressure in the district? General Comment:	General Comment:		
district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to indicate the gas pressure in the district? Not Application	USDI has evaluated the pressure regulation and overpre	essure protection present to ensure they have sufficient capacity.	
N/A All of the White County systems each have one source of supply. They are not currently monitored using pressure recording devices. [192.603(b)][192.741(c)] If there were indications of abnormally high- or low-pressure, were actions taken to correct any unsatisfactory operating conditions? [192.603(b)][192.743(a),192.743(b),192.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [192.603(b)][192.743(a)] If Yes, does the operator have documentation to verify that these devices have adequate capacity? [192.603(b)][192.743(a)] Satisfactors of unusually high pressures were reported in 2011-2013. [192.603(b)][192.743(a)] If Yes, does the operator have documentation to verify that these devices have adequate capacity? Satisfactors of the take point? [192.603(b)][192.747(a),192.747(b)] Did the operator inspect and maintain distribution valves	[192.603(b)][192.741(a),192.741(b)]	district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure	Not Applicable
[192.603(b)][192.741(c)] If there were indications of abnormally high- or low-pressure, were actions taken to correct any unsatisfactory operating conditions? Not Application of unusually high pressures were reported in 2011-2013.	General Comment:	•	
pressure, were actions taken to correct any unsatisfactory operating conditions? Continuous properties of unusually high pressures were reported in 2011-2013.	N/A All of the White County systems each have one sout	rce of supply. They are not currently monitored using pressure recording devices.	
[192.603(b)][192.743(a),192.743(b),192.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [192.603(b)][192.743(a)] If Yes, does the operator have documentation to verify that these devices have adequate capacity? [192.603(b)][192.743(a)] Satisfactor Sat	[192.603(b)][192.741(c)]	pressure, were actions taken to correct any unsatisfactory	Not Applicable
[192.603(b)][192.743(a),192.743(b),192.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [192.603(b)][192.743(a)] If Yes, does the operator have documentation to verify that these devices have adequate capacity? [192.603(b)][192.743(a)] Satisfactor of the take point? [192.603(b)][192.743(a)] If Yes, does the operator have documentation to verify that these devices have adequate capacity? [192.603(b)][192.743(a)] Satisfactor of the take point? [192.603(b)][192.747(a),192.747(b)] Did the operator inspect and maintain distribution valves	General Comment:		
downstream of the take point? [192.603(b)][192.743(a)] If Yes, does the operator have documentation to verify that these devices have adequate capacity? Satisfactor Satisfactor Substitution of the take point? Satisfactor Satisfactor Substitution of the take point? Satisfactor Satisfactor Substitution of the take point? Satisfactor Substitution of the take point? Satisfactor Satisfactor Substitution of the take point? Satisfactor Satisfactor Substitution of the take point? Satisfactor Substitution of the take point? Satisfactor Satisfactor Substitution of the take point? S	No reports of unusually high pressures were reported in	2011-2013.	
these devices have adequate capacity? General Comment: USDI is to conduct a review the master meter installations and determine if they have adequate capacity to provide overpressure protection and determine separate relief devices are present. If inadequate capacities are present, addition protection shall be installed. VALVE MAINTENANCE Status [192.603(b)][192.747(a),192.747(b)] Did the operator inspect and maintain distribution valves	[192.603(b)][192.743(a),192.743(b),192.195(l		Yes
USDI is to conduct a review the master meter installations and determine if they have adequate capacity to provide overpressure protection and determine is separate relief devices are present. If inadequate capacities are present, addition protection shall be installed. VALVE MAINTENANCE Status [192.603(b)][192.747(a),192.747(b)] Did the operator inspect and maintain distribution valves	[192.603(b)][192.743(a)]		Satisfactory
separate relief devices are present. If inadequate capacities are present, addition protection shall be installed. VALVE MAINTENANCE Status [192.603(b)][192.747(a),192.747(b)] Did the operator inspect and maintain distribution valves	General Comment:	•	
[192.603(b)][192.747(a),192.747(b)] Did the operator inspect and maintain distribution valves			n and determine if
	VAL	VE MAINTENANCE	Status
minimum of 1 per year/15 months?	[192.603(b)][192.747(a),192.747(b)]	necessary for the safe operation of the system at a	Satisfactory

General Comment:		
	2044 2040	
Valve inspections were performed as required in	2011-2013.	
[192.603(b)][192.749(a)]	Did the operator inspect and maintain vaults > 200 cubic feet at a minimum of 1 per year/15 months?	Not Applicable
General Comment:		
N/A No Vaults in the White County Housing syste	ems.	
Investigation Of Failures		Status
[192.603(b)][192.617]	Did the operator experience accidents or failures requiring analysis?	Satisfactory
General Comment:		I
There were no equipment or fitting failures or inci master meter. This was replaced and recoated.	idents in 2011-2013. The only leak was established to be due to disbonded coating on th	e outlet riser of the
\	WELDING OF STEEL PIPE	Status
[192.603(b)][192.225(b)]	Does the operator have documentation for their qualified welding procedure?	Satisfactory
General Comment:	<u> </u>	
White County has adopted qualified welding proc	redures.	
[192.603(b)][192.227,192.229]	Does the operator have documentation of welder qualification documentation as required?	Satisfactory
General Comment:		•
White County utilizes Illinois Gas welders and Mr	. Hughes who completed the leak repair in 2012 was qualified.	
[192.709][192.243(b)(2)]	Does the operator have documentation of NDT personnel qualification as required?	Not Applicable
General Comment:		
N/A NDT testing is not required on distribution sy	stems.	
[192.709][192.243(f)]	Does the operator have documentation of NDT testing performed?	Not Applicable
General Comment:		
N/A No NDT testing was performed / required in 2	2011-2013.	
JOINING OF MATERIAL OTHER THAN WELDING		Status
Category Comment:		
No plastic piping was installed in the White Coun	ty systems in 2011-2013.	
[192.603(b)][192.285]	Are persons making joints with plastic pipe qualified?	Not Applicable

[192.603(b)][192.287]	Are persons inspecting plastic pipe joints qualified?	Not Applicable
[192.603(b)][192.283]	Are qualified joining procedures for plastic pipe in place?	Not Applicable
General Comment:		
The White County O&M has qualified joining proce	dures in place.	
CORR	OSION CONTROL RECORDS	Status
[192.491(a)][192.491(a)]	Has the operator maintained maps or records of cathodically protected piping, cathodic protection facilities, galvanic anodes, and neighboring structures bonded to the cathodic protection system?	Satisfactory
General Comment:	·	
White County / USDI have current maps of the sys	tems and the necessary documentation for the corrosion systems protecting their facilities	9S.
[192.491][192.459]	Has the operator maintained documentation of an examination when buried pipe was exposed?	Not Applicable
General Comment:		
No buried pipe was exposed in 2011-2013 to inspe	ect. The one repair completed in 2012 was on above ground riser piping.	
[192.491][192.465(a)]	Has the operator maintained documentation of annual pipe-to-soil monitoring performed at a minimum of 1 per yr/15 months and/or isolated services or short sections of main less than 100 feet at a minimum of 10% annually?	Satisfactory
General Comment: All piping in each system is protected as a single sabove -1volt.	ystem. Annual pipe to soil surveys were conducted in 2011-2013 as required and indica	te potentials at or
[192.491][192.465(b)]	Has the operator maintained documentation of rectifier or other impressed current power sources inspections at a minimum of 6 per year/ 2 1/2 months?	Not Applicable
General Comment:	•	
N/A No rectifiers in the White County Systems.		
[192.491][192.465(c)]	Has the operator maintained documentation of each critical interference bond, reverse current switch, diode, etc. inspections at a minimum of 6 per year/ 2 1/2 months and/or non-critical interference bond inspections at a minimum of 1 per year/15 months?	Not Applicable
General Comment:		
N/A There are no critical or non-critical bonds in th	e White County systems.	

No deficiencies were identified during the monitoring perfor	med in 2011-2013.	
[192.491][192.465(e)]	Has the operator maintained documentation of unprotected pipeline surveys, inspections, or tests at a minimum of 3 years/39 months?	Not Applicable
General Comment:		
N/A There is no unprotected piping in the White County sys	stems.	
[192.491][192.467(a),192.467(c),192.467(d)]	Has the operator maintained documentation of inspections or tests for electrical isolation at casings?	Not Applicable
General Comment:	•	
There are no casings in the White County systems.		
[192.491][192.469]	Does the operator have a sufficient number of test stations or other contact points for electrical measurement to determine the adequacy of cathodic protection?	Satisfactory
General Comment:	·	
Each riser connected to the protected steel system are utilized.	zed for test points and were read in each system annually in 2011-2013.	
[192.491][192.471]	Has the operator maintained documentation of corrective actions taken when a test lead is no longer electrically conductive?	Not Applicable
General Comment:	•	
No issues with test leads were identified during the monitor	ing performed in 2011-2013.	
[192.491][192.473(b)]	Has the operator maintained documentation of inspections or tests to assure their cathodic protection system is not affecting adjacent underground metallic structures?	Satisfactory
General Comment:		
The White County systems are protected using anodes and	tests are performed to ensure they are not affecting the municipals systems.	
[192.491][192.475(a)]	Has the operator maintained documentation of investigations or steps taken to minimize internal corrosion due to transportation of corrosive gas?	Not Applicable
General Comment:	•	
N/A White County receives pipeline quality gas from the mu	unicipal systems. They are not transporting corrosive gas.	
[192.491][192.475(b)]	Has the operator maintained documentation of internal surface inspections performed when pipe is removed for any reason?	Satisfactory
General Comment:		
Yes, the segment removed in 2012 was inspected and dete no issues with internal corrosion.	ermined to be due to external corrosion. A pipe exam sheet was completed as r	equired and indicated
[192.491][192.477]	Has the operator maintained documentation of internal	Not Applicable

	corrosion coupon monitoring at a minimum of 2 per year/ 7			
	1/2 months?			
General Comment:				
N/A They are not transporting corrosive gas so coupons are not utilized. They have reported no indications of leakage or observations identifying wall loss due to internal corrosion.				
[192.491][192.481]	Has the operator maintained documentation of atmospheric corrosion control monitoring at a minimum of 1 per 3 years/ 39 months?	Satisfactory		
General Comment:				
Atmospheric corrosion surveys were performed in 2008 and 2	2011 no issues was reported.			
[192.491][192.479]	Has the operator maintained documentation of corrective action where atmospheric corrosion was discovered?	Satisfactory		
General Comment:				
The only corrosion observed was due to disbonded hot wrap coating that retained moisture and resulted in corrosion on a riser at the master meter at Martin and 3rd Street in Grayville, Illinois. The corrosion was initially repaired using a leak clamp, was later replaced with a new segment of steel piping and was recoated to protect against corrosion.				
[192.491][192.483(a),192.483(b),192.483(c)]	Has the operator maintained documentation demonstrating that pipe removed due to external corrosion has been repaired or replaced with pipe that was coated and cathodically protected?	Satisfactory		
General Comment:				
Documentation was completed indicating the external corrosi corrosion.	ion was replaced with a new segment of piping and was recoated to protect ag	ainst atmospheric		
TRAINING - 83 IL ADM. CODE 520		Status		
[520.10(a) (1)]	Has the operator maintained documentation demonstrating that personnel have received adequate training?	Satisfactory		
General Comment:				
Staff reviewed the training records maintained for the Illinois	Gas and USDI employees. No issues were identified.			
[520.10(a) (2)]	Do training records include verbal instruction and/or on the job training for each job classification?	Satisfactory		
General Comment:				
Yes, Illinois Gas is recording when verbal instruction is provide	ded.			
[520.10(b)]	Has the municipal operator maintained documentation demonstrating that personnel have received adequate training?	Not Applicable		
General Comment:				
USDI / Illinois Gas is not a municipal operator. They do have training requirements specified in their training program.				
[520.10(a)(5)]	Are procedures periodically updated to include new materials, new methods of operation and installation, and	Satisfactory		

	changes in general procedures?				
General Comment:					
Illinois Gas / USDI does perform training when procedures are revised or new procedures or equipment is utilized.					